



Damage to the roof at the intake building at O.B. Curtis



The repaired intake building at O.B. Curtis



A diver preparing to inspect the intake structure at O.B. Curtis

Intake Structure Repairs

Assess and repair, as necessary, the intake structures at J.H. Fewell and O.B. Curtis.

Completed repairs at J.H. Fewell and O.B. Curtis in accordance with recommended actions.

Project Information

Current % Complete: 100%

Completion Date: February 2, 2026

Contractor: Jacobs, UESI, and ASI Marine

Find us:



Key Project Highlights

- Repaired the roof and lighting for O.B. Curtis
- Performed a structural inspection of the intake support structure below the water line at O.B. Curtis
- Rehabilitated the permanganate feed system